




1917-0







08/18

- Montageanleitung
- Assembly instructions
- Notice de montage
- Montagehandleiding
- Návod na montáž
- Instrucțiune de montaj
- Navodila za namestitev
- Installationstruktioener











Pos. 1










x1







Pos. 2





















x1


































































Pos. 34




2,5 mm






X1

















Pos. 35




X2









Notizen, notes, notities




Notizen, notes, notities



Notizen, notes, notities





1917-0

Kontrollbeleg
Control Receipt

Prüfnummer/ Inspection number



Service
Am Lindhövel 1
59846 Sundern
Deutschland / Germany / Allemagne / Duitsland



Allgemeine technische Probleme:
Telefon 02935 / 96 53 444



E-Mail:
onlineservice@schulte.de